

Center Point Display (Simple Measurement)



There is a center point display in the 'Simple Measurement' tool in the file quick toolbar.

In addition to displaying the image center point, it is possible to display a cross cursor at two specific points.

